


Front View




Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Rear View



Missing


Spindles not original to desk

Add-ons

Inscriptions



Top



■ Loose/broken/delaminated

■ Damage/wear/hole

■ Previous repair

■ Replaced piece


■ Missing

■ Spindles not original to desk


■ Add-ons

■ Inscriptions

Bottom



Bottom



■ Loose/broken/delaminated

■ Damage/wear/hole

■ Previous repair

■ Replaced piece

■ Missing

■ Spindles not original to desk


■ Add-ons

■ Inscriptions

Drawer Front, Outer Surface



Rear Surface of Drawer Front



■ Loose/broken/delaminated

■ Damage/wear/hole

■ Previous repair

■ Replaced piece

■ Missing



■ Spindles not original to desk

■ Add-ons

■ Inscriptions

Inside Surface of Left Drawer Side

Inside Surface of Right Drawer Side



Loose/broken/delaminated

Previous repair

Missing

Add-ons


Damage/wear/hole

Replaced piece








Spindles not original to desk

Inscriptions

Rear Surface of Drawer Back





Front Surface of Drawer Back

 Loose/broken/delaminated Previous repair Missing Add-ons Damage/wear/hole Replaced piece Spindles not original to desk Inscriptions

Upper Surface of Drawer Bottom

Lower Surface : of Drawer Bottom



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons

■ Damage/wear/hole

■ Replaced piece








■ Spindles not original to desk

■ Inscriptions



Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side

 Loose/broken/delaminated Previous repair Missing Add-ons Damage/wear/hole Replaced piece Spindles not original to desk Inscriptions